

Internal  
S/035/0028



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

### Inspection Report Minerals Regulatory Program June 7, 2010

Reviewed: FRB

<b>Mine Name:</b> Donna Gibson	<b>Permit Number:</b> S/035/0028
<b>Operator Name:</b> Jared Stoddard	<b>Inspection Date:</b> April 22, 2010
<b>Inspector(s):</b> L Heppler	<b>Time:</b> 8:00 am
<b>Other Participants:</b> none	<b>Mine Status:</b> Active – Inspection requested

#### Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)
8. Soils
9. Revegetation

#### Evaluated

#### Comment

#### Enforcement

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Amount:** \$5,000 **Permit fee** is up to date (inspect status requested)

**Purpose of Inspection:** Routine annual Inspection. This site was inspected as a small mine site on 10/27/2009

**Inspection Summary:** This site has been regraded, but not revegetated.

Photos were taken to document site conditions.

**Conclusions and Recommendations:** The permitted Operator had originally reclaimed this 3 acre site, when a second Operator mined rock from the location (1 acre), before an inspection was requested from OGM. A third Operator recently reclaimed the site for the permitted Operator. A bond release can be done for the regraded site. Revegetation bond to remain is \$2,000 (\$1000 mob & \$1000 per acre for seed). OGM to continue annual inspections and monitor the site when in the area.

**Inspector's Signature**

LAH:vs

cc: Jared Stoddard

O:\M035-SaltLake\S0350028-DonnaGibson\inspections\Insp-04222010.doc

